
## Figure 12 Pull Assembly



Steel posts must be painted or galvanized if  $< \frac{1}{4}$  in. wall thickness.